OMRON

Omron 'virtual hands on' distance learning service.

	er Simulation Tools Window Help 人品區區盤A 00 尾(人) (本文) (4)	# * * 0 9 2 1 2 2 2 4	©	ځ
	Relative_MC - Motion ×		v Toolbox ······· v 9	
Varia	bles		▲ <search> ▼ 𝔍 🗙</search>	
Node21 : NX-ECC	DiskRealtive MC_MoveRelative		Analog Conversion	T
Node21 : NX-ECC (i) Node22 : R88D-1	DiskRelMove Disk	lais — Disk	BCD Conversion	and the second se
Mode22 : R88D-1 Mode23 : R88D-1		one		
CPU/Expansion Rack:		usy — Enter Variable	► Bit String Processing	
▶ == CPU Rack			Communications	
e* I/O Map		We — Enter Variable	► Comparison	
🕄 Controller Setup	(360) DiskAcc—Acceleration CommandAbo	ted —Enter Variable	auto	
Motion Control Setup	(360) DiskDec— Deceleration E	ror — Enter Variable	► Conversion	9/90
▼ ⊕ Axis Settings	Enter Variable—Jerk Err	nD_Enter Variable	► Counter 0	
L 你 Disk (0)	Enter Variable BufferMode		► Data Movement	Childrammonstituentes
L 你 Belt (1) L 偽 Axes Group Settir	Enter Vontoole Duiterwode		Data Type Conversion	
e' Cam Data Settings				Statement of the local division of the local
 Event Settings 			DB Connect	
Task Settings			► FCS	
M Data Trace Settings			Ladder Tools	
Host Connection Sett			VI 192.168.250.2 (Compact) - VNC Viewer	- 0
ramming				A A A A A A A A A A A A A A A A A A A
POUs				mac Motion Introduction
▼ 🕄 Programs			► 0t - M	C_MoveRelative -
V 🖽 Motion			Pro Di Luca Luca Disk.Ditals.Horrad	
L 쿱·PLCerror L 쿱·MCerror			Disk (Sysmac Axis U)	Co Co Co Co Co Belt (Sysmac Axis 1) Belt DetailsHomed BettOrdstatuReady
L & ECerror			0118.36 deg 0118.36 deg Disk.DristatusServoOn	0000.00 mm 0000.00 mm Beit.Driftatus.SevoOn
L & ElPerror			Se 0000.00 deg/s 0000.00 deg/s DiskStatusStandstill O	Troubleshooter 000102 mm/s 0000.02 mm/s Bet/Status Standstill 000.0 % 000.0 % Bet/DroStatus MainPower
L & ClBerror			Se COLON COLON COLON COLONGELE MANYOWER	COLON BALLYSING MANYOW
L 🔄 Errors				
L @ Power_MC			MC_Power MC_Home MC_MoveJog MC_MoveVelocity MC_MoveRe	ative MC_MoveAbsolute MC_MoveFeed MC_TouchProbe MC_SetTorqueLimit MC_TorqueCo
∟ & Home_MC				
L @- JogMC				DiskDitance -360 deg
L @· MoveVelo			DiskRelMove	BeltRelMove DiskVelocity 50 deg/s
L C MoveRelat				204-64
build			- 7 × Contro DISK	BELI
- DO F	rors 10 Warnings			
Data	I Description I Program I	Location I	ONI	BeltDistance 400 mm
L 5량 Data Types				itatus.Discrete 🕘 BeltVelocity 400 mm/s
L test Global Variables				Dir Nega 💿 BeltAcc 400 mm/k/s
🖽 Tasks				BeltDec 400 mm/s/s
🕨 🖿 PrimaryTask				
>				
Cutput	Build			

Omron are pleased to offer a new training experience. Our training courses are now available as remote courses, delivered to you at your home, office or factory.

Our training ethos has always been 'learn by doing', a hands-on approach to learning.

"For the things we have to learn before we can do them, we learn by doing them." - Aristotle

With the use of technology, we can now offer a 'virtual hands-on' learning, close to a traditional face to face classroom experience.

Omron UK Onron UK Onron 258 258 uk@omron.com industrial.omron.co.uk You will be invited to the training via a Microsoft Teams meeting, whilst in parallel you will connect to one of our training laptops using a remote desktop (teamviewer).

The desktop will have the all programming software required for your training, along with a live video feed from the training equipment.

You only need to download a free copy of teamviewer to access our laptop prior to the training, and attend the teams meeting on the day.

All details are sent to you on our course booking confirmation email, including links to software downloads, prior to your attendance.

No hotels, no restaurants, no additional travel.

Please contact a member of the Omron Training Department for details:

By phone on 01908 258 258 By email at UK_Training@Omron.com

Via our website, by way of the course enquiry form at industrial.omron.co.uk/training