

Product Discontinuation

Safety Mat

UMA series



Recommended Replacement

No recommended replacement

[Final order entry date]

The end of June, 2024

[Date of The Last Shipping]

The end of September, 2024

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement
MC3	No recommended replacement
MTKCA-0300-0250	No recommended replacement
MTKCA-0300-0300	No recommended replacement
MTKCA-0300-1250	No recommended replacement
MTKCA-0300-1500	No recommended replacement
MTKCA-0300-1750	No recommended replacement
MTKCA-0300-1800	No recommended replacement
MTKCA-0400-0250	No recommended replacement
MTKCA-0400-0300	No recommended replacement
MTKCA-0400-0400	No recommended replacement
MTKCA-0400-1250	No recommended replacement
MTKCA-0400-1500	No recommended replacement
MTKCA-0400-1750	No recommended replacement
MTKCA-0400-1800	No recommended replacement
MTKCA-0500-0250	No recommended replacement
MTKCA-0500-0300	No recommended replacement
MTKCA-0500-0400	No recommended replacement
MTKCA-0500-0500	No recommended replacement
MTKCA-0500-1250	No recommended replacement
MTKCA-0500-1500	No recommended replacement
MTKCA-0500-1750	No recommended replacement
MTKCA-0500-1800	No recommended replacement
MTKCA-0600-0250	No recommended replacement
MTKCA-0600-0300	No recommended replacement
MTKCA-0600-0400	No recommended replacement
MTKCA-0600-0500	No recommended replacement
MTKCA-0600-0600	No recommended replacement
MTKCA-0600-1250	No recommended replacement
MTKCA-0600-1500	No recommended replacement
MTKCA-0600-1750	No recommended replacement

Product discontinuation	Recommended replacement
MTKCA-0600-1800	No recommended replacement
MTKCA-0750-0250	No recommended replacement
MTKCA-0750-0300	No recommended replacement
MTKCA-0750-0400	No recommended replacement
MTKCA-0750-0500	No recommended replacement
MTKCA-0750-0600	No recommended replacement
MTKCA-0750-0750	No recommended replacement
MTKCA-0750-1250	No recommended replacement
MTKCA-0750-1500	No recommended replacement
MTKCA-0750-1750	No recommended replacement
MTKCA-0750-1800	No recommended replacement
MTKCA-0800-0250	No recommended replacement
MTKCA-0800-0300	No recommended replacement
MTKCA-0800-0400	No recommended replacement
MTKCA-0800-0500	No recommended replacement
MTKCA-0800-0600	No recommended replacement
MTKCA-0800-0750	No recommended replacement
MTKCA-0800-0800	No recommended replacement
MTKCA-0800-1250	No recommended replacement
MTKCA-0800-1500	No recommended replacement
MTKCA-0800-1750	No recommended replacement
MTKCA-0800-1800	No recommended replacement
MTKCA-0900-0250	No recommended replacement
MTKCA-0900-0300	No recommended replacement
MTKCA-0900-0400	No recommended replacement
MTKCA-0900-0500	No recommended replacement
MTKCA-0900-0600	No recommended replacement
MTKCA-0900-0750	No recommended replacement
MTKCA-0900-0800	No recommended replacement
MTKCA-0900-0900	No recommended replacement
MTKCA-0900-1250	No recommended replacement
MTKCA-0900-1500	No recommended replacement
MTKCA-0900-1750	No recommended replacement
MTKCA-0900-1800	No recommended replacement
MTKCA-1000-0250	No recommended replacement
MTKCA-1000-0300	No recommended replacement
MTKCA-1000-0400	No recommended replacement
MTKCA-1000-0500	No recommended replacement
MTKCA-1000-0600	No recommended replacement
MTKCA-1000-0750	No recommended replacement
MTKCA-1000-0800	No recommended replacement
MTKCA-1000-0900	No recommended replacement
MTKCA-1000-1000	No recommended replacement
MTKCA-1000-1250	No recommended replacement
MTKCA-1000-1500	No recommended replacement
MTKCA-1000-1750	No recommended replacement
MTKCA-1000-1800	No recommended replacement
MTKCA-1100-0250	No recommended replacement
MTKCA-1100-0300	No recommended replacement

Product discontinuation	Recommended replacement
MTKCA-1100-0400	No recommended replacement
MTKCA-1100-0500	No recommended replacement
MTKCA-1100-0600	No recommended replacement
MTKCA-1100-0750	No recommended replacement
MTKCA-1100-0800	No recommended replacement
MTKCA-1100-0900	No recommended replacement
MTKCA-1100-1000	No recommended replacement
MTKCA-1100-1250	No recommended replacement
MTKCA-1100-1500	No recommended replacement
MTKCA-1100-1750	No recommended replacement
MTKCA-1100-1800	No recommended replacement
MTKCA-1200-0250	No recommended replacement
MTKCA-1200-0300	No recommended replacement
MTKCA-1200-0400	No recommended replacement
MTKCA-1200-0500	No recommended replacement
MTKCA-1200-0600	No recommended replacement
MTKCA-1200-0750	No recommended replacement
MTKCA-1200-0800	No recommended replacement
MTKCA-1200-0900	No recommended replacement
MTKCA-1200-1000	No recommended replacement
MTKCA-1200-1250	No recommended replacement
MTKCA-1200-1500	No recommended replacement
MTKCA-1200-1750	No recommended replacement
MTKCA-1200-1800	No recommended replacement
MTKMA-0300-0250	No recommended replacement
MTKMA-0300-0300	No recommended replacement
MTKMA-0300-1250	No recommended replacement
MTKMA-0300-1500	No recommended replacement
MTKMA-0300-1750	No recommended replacement
MTKMA-0300-1800	No recommended replacement
MTKMA-0400-0250	No recommended replacement
MTKMA-0400-0300	No recommended replacement
MTKMA-0400-0400	No recommended replacement
MTKMA-0400-1250	No recommended replacement
MTKMA-0400-1500	No recommended replacement
MTKMA-0400-1750	No recommended replacement
MTKMA-0400-1800	No recommended replacement
MTKMA-0500-0250	No recommended replacement
MTKMA-0500-0300	No recommended replacement
MTKMA-0500-0400	No recommended replacement
MTKMA-0500-0500	No recommended replacement
MTKMA-0500-1250	No recommended replacement
MTKMA-0500-1500	No recommended replacement
MTKMA-0500-1750	No recommended replacement
MTKMA-0500-1800	No recommended replacement
MTKMA-0600-0250	No recommended replacement
MTKMA-0600-0300	No recommended replacement
MTKMA-0600-0400	No recommended replacement
MTKMA-0600-0500	No recommended replacement

Product discontinuation	Recommended replacement
MTKMA-0600-0600	No recommended replacement
MTKMA-0600-1250	No recommended replacement
MTKMA-0600-1500	No recommended replacement
MTKMA-0600-1750	No recommended replacement
MTKMA-0600-1800	No recommended replacement
MTKMA-0750-0250	No recommended replacement
MTKMA-0750-0300	No recommended replacement
MTKMA-0750-0400	No recommended replacement
MTKMA-0750-0500	No recommended replacement
MTKMA-0750-0600	No recommended replacement
MTKMA-0750-0750	No recommended replacement
MTKMA-0750-1250	No recommended replacement
MTKMA-0750-1500	No recommended replacement
MTKMA-0750-1750	No recommended replacement
MTKMA-0750-1800	No recommended replacement
MTKMA-0800-0250	No recommended replacement
MTKMA-0800-0300	No recommended replacement
MTKMA-0800-0400	No recommended replacement
MTKMA-0800-0500	No recommended replacement
MTKMA-0800-0600	No recommended replacement
MTKMA-0800-0750	No recommended replacement
MTKMA-0800-0800	No recommended replacement
MTKMA-0800-1250	No recommended replacement
MTKMA-0800-1500	No recommended replacement
MTKMA-0800-1750	No recommended replacement
MTKMA-0800-1800	No recommended replacement
MTKMA-0900-0250	No recommended replacement
MTKMA-0900-0300	No recommended replacement
MTKMA-0900-0400	No recommended replacement
MTKMA-0900-0500	No recommended replacement
MTKMA-0900-0600	No recommended replacement
MTKMA-0900-0750	No recommended replacement
MTKMA-0900-0800	No recommended replacement
MTKMA-0900-0900	No recommended replacement
MTKMA-0900-1250	No recommended replacement
MTKMA-0900-1500	No recommended replacement
MTKMA-0900-1750	No recommended replacement
MTKMA-0900-1800	No recommended replacement
MTKMA-1000-0250	No recommended replacement
MTKMA-1000-0300	No recommended replacement
MTKMA-1000-0400	No recommended replacement
MTKMA-1000-0500	No recommended replacement
MTKMA-1000-0600	No recommended replacement
MTKMA-1000-0750	No recommended replacement
MTKMA-1000-0800	No recommended replacement
MTKMA-1000-0900	No recommended replacement
MTKMA-1000-1000	No recommended replacement
MTKMA-1000-1250	No recommended replacement
MTKMA-1000-1500	No recommended replacement

Product discontinuation	Recommended replacement
MTKMA-1000-1750	No recommended replacement
MTKMA-1000-1800	No recommended replacement
MTKMA-1100-0250	No recommended replacement
MTKMA-1100-0300	No recommended replacement
MTKMA-1100-0400	No recommended replacement
MTKMA-1100-0500	No recommended replacement
MTKMA-1100-0600	No recommended replacement
MTKMA-1100-0750	No recommended replacement
MTKMA-1100-0800	No recommended replacement
MTKMA-1100-0900	No recommended replacement
MTKMA-1100-1000	No recommended replacement
MTKMA-1100-1250	No recommended replacement
MTKMA-1100-1500	No recommended replacement
MTKMA-1100-1750	No recommended replacement
MTKMA-1100-1800	No recommended replacement
MTKMA-1200-0250	No recommended replacement
MTKMA-1200-0300	No recommended replacement
MTKMA-1200-0400	No recommended replacement
MTKMA-1200-0500	No recommended replacement
MTKMA-1200-0600	No recommended replacement
MTKMA-1200-0750	No recommended replacement
MTKMA-1200-0800	No recommended replacement
MTKMA-1200-0900	No recommended replacement
MTKMA-1200-1000	No recommended replacement
MTKMA-1200-1250	No recommended replacement
MTKMA-1200-1500	No recommended replacement
MTKMA-1200-1750	No recommended replacement
MTKMA-1200-1800	No recommended replacement
UMA-12-12-1	No recommended replacement
UMA-12-12-2	No recommended replacement
UMA-12-18-1	No recommended replacement
UMA-12-18-2	No recommended replacement
UMA-12-24-1	No recommended replacement
UMA-12-24-2	No recommended replacement
UMA-12-30-1	No recommended replacement
UMA-12-30-2	No recommended replacement
UMA-12-36-1	No recommended replacement
UMA-12-36-2	No recommended replacement
UMA-12-42-1	No recommended replacement
UMA-12-42-2	No recommended replacement
UMA-12-48-1	No recommended replacement
UMA-12-48-2	No recommended replacement
UMA-12-54-1	No recommended replacement
UMA-12-54-2	No recommended replacement
UMA-12-60-1	No recommended replacement
UMA-12-60-2	No recommended replacement
UMA-12-66-1	No recommended replacement
UMA-12-66-2	No recommended replacement
UMA-12-72-1	No recommended replacement

Product discontinuation	Recommended replacement
UMA-12-72-2	No recommended replacement
UMA-18-12-1	No recommended replacement
UMA-18-12-2	No recommended replacement
UMA-18-18-1	No recommended replacement
UMA-18-18-2	No recommended replacement
UMA-18-24-1	No recommended replacement
UMA-18-24-2	No recommended replacement
UMA-18-30-1	No recommended replacement
UMA-18-30-2	No recommended replacement
UMA-18-36-1	No recommended replacement
UMA-18-36-2	No recommended replacement
UMA-18-42-1	No recommended replacement
UMA-18-42-2	No recommended replacement
UMA-18-48-1	No recommended replacement
UMA-18-48-2	No recommended replacement
UMA-18-54-1	No recommended replacement
UMA-18-54-2	No recommended replacement
UMA-18-60-1	No recommended replacement
UMA-18-60-2	No recommended replacement
UMA-18-66-1	No recommended replacement
UMA-18-66-2	No recommended replacement
UMA-18-72-1	No recommended replacement
UMA-18-72-2	No recommended replacement
UMA-24-12-1	No recommended replacement
UMA-24-12-2	No recommended replacement
UMA-24-18-1	No recommended replacement
UMA-24-18-2	No recommended replacement
UMA-24-24-1	No recommended replacement
UMA-24-24-2	No recommended replacement
UMA-24-30-1	No recommended replacement
UMA-24-30-2	No recommended replacement
UMA-24-36-1	No recommended replacement
UMA-24-36-2	No recommended replacement
UMA-24-42-1	No recommended replacement
UMA-24-42-2	No recommended replacement
UMA-24-48-1	No recommended replacement
UMA-24-48-2	No recommended replacement
UMA-24-54-1	No recommended replacement
UMA-24-54-2	No recommended replacement
UMA-24-60-1	No recommended replacement
UMA-24-60-2	No recommended replacement
UMA-24-66-1	No recommended replacement
UMA-24-66-2	No recommended replacement
UMA-24-72-1	No recommended replacement
UMA-24-72-2	No recommended replacement
UMA-30-12-1	No recommended replacement
UMA-30-12-2	No recommended replacement
UMA-30-18-1	No recommended replacement
UMA-30-18-2	No recommended replacement

Product discontinuation	Recommended replacement
UMA-30-24-1	No recommended replacement
UMA-30-24-2	No recommended replacement
UMA-30-30-1	No recommended replacement
UMA-30-30-2	No recommended replacement
UMA-30-36-1	No recommended replacement
UMA-30-36-2	No recommended replacement
UMA-30-42-1	No recommended replacement
UMA-30-42-2	No recommended replacement
UMA-30-48-1	No recommended replacement
UMA-30-48-2	No recommended replacement
UMA-30-54-1	No recommended replacement
UMA-30-54-2	No recommended replacement
UMA-30-60-1	No recommended replacement
UMA-30-60-2	No recommended replacement
UMA-30-66-1	No recommended replacement
UMA-30-66-2	No recommended replacement
UMA-30-72-1	No recommended replacement
UMA-30-72-2	No recommended replacement
UMA-36-12-1	No recommended replacement
UMA-36-12-2	No recommended replacement
UMA-36-18-1	No recommended replacement
UMA-36-18-2	No recommended replacement
UMA-36-24-1	No recommended replacement
UMA-36-24-2	No recommended replacement
UMA-36-30-1	No recommended replacement
UMA-36-30-2	No recommended replacement
UMA-36-36-1	No recommended replacement
UMA-36-36-2	No recommended replacement
UMA-36-42-1	No recommended replacement
UMA-36-42-2	No recommended replacement
UMA-36-48-1	No recommended replacement
UMA-36-48-2	No recommended replacement
UMA-36-54-1	No recommended replacement
UMA-36-54-2	No recommended replacement
UMA-36-60-1	No recommended replacement
UMA-36-60-2	No recommended replacement
UMA-36-66-1	No recommended replacement
UMA-36-66-2	No recommended replacement
UMA-36-72-1	No recommended replacement
UMA-36-72-2	No recommended replacement
UMA-42-12-1	No recommended replacement
UMA-42-12-2	No recommended replacement
UMA-42-18-1	No recommended replacement
UMA-42-18-2	No recommended replacement
UMA-42-24-1	No recommended replacement
UMA-42-24-2	No recommended replacement
UMA-42-30-1	No recommended replacement
UMA-42-30-2	No recommended replacement
UMA-42-36-1	No recommended replacement

Product discontinuation	Recommended replacement
UMA-42-36-2	No recommended replacement
UMA-42-42-1	No recommended replacement
UMA-42-42-2	No recommended replacement
UMA-42-48-1	No recommended replacement
UMA-42-48-2	No recommended replacement
UMA-42-54-1	No recommended replacement
UMA-42-54-2	No recommended replacement
UMA-42-60-1	No recommended replacement
UMA-42-60-2	No recommended replacement
UMA-42-66-1	No recommended replacement
UMA-42-66-2	No recommended replacement
UMA-42-72-1	No recommended replacement
UMA-42-72-2	No recommended replacement
UMA-48-12-1	No recommended replacement
UMA-48-12-2	No recommended replacement
UMA-48-18-1	No recommended replacement
UMA-48-18-2	No recommended replacement
UMA-48-24-1	No recommended replacement
UMA-48-24-2	No recommended replacement
UMA-48-30-1	No recommended replacement
UMA-48-30-2	No recommended replacement
UMA-48-36-1	No recommended replacement
UMA-48-36-2	No recommended replacement
UMA-48-42-1	No recommended replacement
UMA-48-42-2	No recommended replacement
UMA-48-48-1	No recommended replacement
UMA-48-48-2	No recommended replacement
UMA-48-54-1	No recommended replacement
UMA-48-54-2	No recommended replacement
UMA-48-60-1	No recommended replacement
UMA-48-60-2	No recommended replacement
UMA-48-66-1	No recommended replacement
UMA-48-66-2	No recommended replacement
UMA-48-72-1	No recommended replacement
UMA-48-72-2	No recommended replacement
UMA-CBL-3PCF-M8-02M	No recommended replacement
UMA-CBL-3PCF-M8-05M	No recommended replacement
UMA-CBL-3PCF-M8-10M	No recommended replacement
UMA-CBL-3PFF-M8-0.15M	No recommended replacement
UMA-CBL-3PMF-M8-02M	No recommended replacement
UMA-CBL-3PMF-M8-05M	No recommended replacement
UMA-CBL-3PMF-M8-10M	No recommended replacement
UMA-CBL-3PMM-M8-0.15M	No recommended replacement
UMA-CBL-4PCF-M8-02M	No recommended replacement
UMA-CBL-4PCF-M8-05M	No recommended replacement
UMA-CBL-4PCF-M8-10M	No recommended replacement
UMA-CBL-4PMF-M8-02M	No recommended replacement
UMA-CBL-4PMF-M8-05M	No recommended replacement
UMA-CBL-4PMF-M8-10M	No recommended replacement

Product discontinuation	Recommended replacement
UMA-SA-4PF-M8-4PM-M12	No recommended replacement
UMA-TRES	No recommended replacement
UMA-YA-3PMF-M8-4PM-M12	No recommended replacement
UMAL	No recommended replacement
UMIC	No recommended replacement
UMJS4	No recommended replacement
UMJS8	No recommended replacement
UMJTC8-B	No recommended replacement
UMJTC8Y	No recommended replacement
UMMA-0300-0250-1	No recommended replacement
UMMA-0300-0250-2	No recommended replacement
UMMA-0300-0300-1	No recommended replacement
UMMA-0300-0300-2	No recommended replacement
UMMA-0300-1250-1	No recommended replacement
UMMA-0300-1250-2	No recommended replacement
UMMA-0300-1500-1	No recommended replacement
UMMA-0300-1500-2	No recommended replacement
UMMA-0300-1750-1	No recommended replacement
UMMA-0300-1750-2	No recommended replacement
UMMA-0300-1800-1	No recommended replacement
UMMA-0300-1800-2	No recommended replacement
UMMA-0400-0250-1	No recommended replacement
UMMA-0400-0250-2	No recommended replacement
UMMA-0400-0300-1	No recommended replacement
UMMA-0400-0300-2	No recommended replacement
UMMA-0400-0400-1	No recommended replacement
UMMA-0400-0400-2	No recommended replacement
UMMA-0400-1250-1	No recommended replacement
UMMA-0400-1250-2	No recommended replacement
UMMA-0400-1500-1	No recommended replacement
UMMA-0400-1500-2	No recommended replacement
UMMA-0400-1750-1	No recommended replacement
UMMA-0400-1750-2	No recommended replacement
UMMA-0400-1800-1	No recommended replacement
UMMA-0400-1800-2	No recommended replacement
UMMA-0500-0250-1	No recommended replacement
UMMA-0500-0250-2	No recommended replacement
UMMA-0500-0300-1	No recommended replacement
UMMA-0500-0300-2	No recommended replacement
UMMA-0500-0400-1	No recommended replacement
UMMA-0500-0400-2	No recommended replacement
UMMA-0500-0500-1	No recommended replacement
UMMA-0500-0500-2	No recommended replacement
UMMA-0500-1250-1	No recommended replacement
UMMA-0500-1250-2	No recommended replacement
UMMA-0500-1500-1	No recommended replacement
UMMA-0500-1500-2	No recommended replacement
UMMA-0500-1750-1	No recommended replacement
UMMA-0500-1750-2	No recommended replacement

Product discontinuation	Recommended replacement
UMMA-0500-1800-1	No recommended replacement
UMMA-0500-1800-2	No recommended replacement
UMMA-0600-0250-1	No recommended replacement
UMMA-0600-0250-2	No recommended replacement
UMMA-0600-0300-1	No recommended replacement
UMMA-0600-0300-2	No recommended replacement
UMMA-0600-0400-1	No recommended replacement
UMMA-0600-0400-2	No recommended replacement
UMMA-0600-0500-1	No recommended replacement
UMMA-0600-0500-2	No recommended replacement
UMMA-0600-0600-1	No recommended replacement
UMMA-0600-0600-2	No recommended replacement
UMMA-0600-1250-1	No recommended replacement
UMMA-0600-1250-2	No recommended replacement
UMMA-0600-1500-1	No recommended replacement
UMMA-0600-1500-2	No recommended replacement
UMMA-0600-1750-1	No recommended replacement
UMMA-0600-1750-2	No recommended replacement
UMMA-0600-1800-1	No recommended replacement
UMMA-0600-1800-2	No recommended replacement
UMMA-0750-0250-1	No recommended replacement
UMMA-0750-0250-2	No recommended replacement
UMMA-0750-0300-1	No recommended replacement
UMMA-0750-0300-2	No recommended replacement
UMMA-0750-0400-1	No recommended replacement
UMMA-0750-0400-2	No recommended replacement
UMMA-0750-0500-1	No recommended replacement
UMMA-0750-0500-2	No recommended replacement
UMMA-0750-0600-1	No recommended replacement
UMMA-0750-0600-2	No recommended replacement
UMMA-0750-0750-1	No recommended replacement
UMMA-0750-0750-2	No recommended replacement
UMMA-0750-1250-1	No recommended replacement
UMMA-0750-1250-2	No recommended replacement
UMMA-0750-1500-1	No recommended replacement
UMMA-0750-1500-2	No recommended replacement
UMMA-0750-1750-1	No recommended replacement
UMMA-0750-1750-2	No recommended replacement
UMMA-0750-1800-1	No recommended replacement
UMMA-0750-1800-2	No recommended replacement
UMMA-0800-0250-1	No recommended replacement
UMMA-0800-0250-2	No recommended replacement
UMMA-0800-0300-1	No recommended replacement
UMMA-0800-0300-2	No recommended replacement
UMMA-0800-0400-1	No recommended replacement
UMMA-0800-0400-2	No recommended replacement
UMMA-0800-0500-1	No recommended replacement
UMMA-0800-0500-2	No recommended replacement
UMMA-0800-0600-1	No recommended replacement

Product discontinuation	Recommended replacement
UMMA-0800-0600-2	No recommended replacement
UMMA-0800-0750-1	No recommended replacement
UMMA-0800-0750-2	No recommended replacement
UMMA-0800-0800-1	No recommended replacement
UMMA-0800-0800-2	No recommended replacement
UMMA-0800-1250-1	No recommended replacement
UMMA-0800-1250-2	No recommended replacement
UMMA-0800-1500-1	No recommended replacement
UMMA-0800-1500-2	No recommended replacement
UMMA-0800-1750-1	No recommended replacement
UMMA-0800-1750-2	No recommended replacement
UMMA-0800-1800-1	No recommended replacement
UMMA-0800-1800-2	No recommended replacement
UMMA-0900-0250-1	No recommended replacement
UMMA-0900-0250-2	No recommended replacement
UMMA-0900-0300-1	No recommended replacement
UMMA-0900-0300-2	No recommended replacement
UMMA-0900-0400-1	No recommended replacement
UMMA-0900-0400-2	No recommended replacement
UMMA-0900-0500-1	No recommended replacement
UMMA-0900-0500-2	No recommended replacement
UMMA-0900-0600-1	No recommended replacement
UMMA-0900-0600-2	No recommended replacement
UMMA-0900-0750-1	No recommended replacement
UMMA-0900-0750-2	No recommended replacement
UMMA-0900-0800-1	No recommended replacement
UMMA-0900-0800-2	No recommended replacement
UMMA-0900-0900-1	No recommended replacement
UMMA-0900-0900-2	No recommended replacement
UMMA-0900-1250-1	No recommended replacement
UMMA-0900-1250-2	No recommended replacement
UMMA-0900-1500-1	No recommended replacement
UMMA-0900-1500-2	No recommended replacement
UMMA-0900-1750-1	No recommended replacement
UMMA-0900-1750-2	No recommended replacement
UMMA-0900-1800-1	No recommended replacement
UMMA-0900-1800-2	No recommended replacement
UMMA-1000-0250-1	No recommended replacement
UMMA-1000-0250-2	No recommended replacement
UMMA-1000-0300-1	No recommended replacement
UMMA-1000-0300-2	No recommended replacement
UMMA-1000-0400-1	No recommended replacement
UMMA-1000-0400-2	No recommended replacement
UMMA-1000-0500-1	No recommended replacement
UMMA-1000-0500-2	No recommended replacement
UMMA-1000-0600-1	No recommended replacement
UMMA-1000-0600-2	No recommended replacement
UMMA-1000-0750-1	No recommended replacement
UMMA-1000-0750-2	No recommended replacement

Product discontinuation	Recommended replacement
UMMA-1000-0800-1	No recommended replacement
UMMA-1000-0800-2	No recommended replacement
UMMA-1000-0900-1	No recommended replacement
UMMA-1000-0900-2	No recommended replacement
UMMA-1000-1000-1	No recommended replacement
UMMA-1000-1000-1-A	No recommended replacement
UMMA-1000-1000-2	No recommended replacement
UMMA-1000-1250-1	No recommended replacement
UMMA-1000-1250-2	No recommended replacement
UMMA-1000-1500-1	No recommended replacement
UMMA-1000-1500-2	No recommended replacement
UMMA-1000-1750-1	No recommended replacement
UMMA-1000-1750-2	No recommended replacement
UMMA-1000-1800-1	No recommended replacement
UMMA-1000-1800-2	No recommended replacement
UMMA-1100-0250-1	No recommended replacement
UMMA-1100-0250-2	No recommended replacement
UMMA-1100-0300-1	No recommended replacement
UMMA-1100-0300-2	No recommended replacement
UMMA-1100-0400-1	No recommended replacement
UMMA-1100-0400-2	No recommended replacement
UMMA-1100-0500-1	No recommended replacement
UMMA-1100-0500-2	No recommended replacement
UMMA-1100-0600-1	No recommended replacement
UMMA-1100-0600-2	No recommended replacement
UMMA-1100-0750-1	No recommended replacement
UMMA-1100-0750-2	No recommended replacement
UMMA-1100-0800-1	No recommended replacement
UMMA-1100-0800-2	No recommended replacement
UMMA-1100-0900-1	No recommended replacement
UMMA-1100-0900-2	No recommended replacement
UMMA-1100-1000-1	No recommended replacement
UMMA-1100-1000-2	No recommended replacement
UMMA-1100-1250-1	No recommended replacement
UMMA-1100-1250-2	No recommended replacement
UMMA-1100-1500-1	No recommended replacement
UMMA-1100-1500-2	No recommended replacement
UMMA-1100-1750-1	No recommended replacement
UMMA-1100-1750-2	No recommended replacement
UMMA-1100-1800-1	No recommended replacement
UMMA-1100-1800-2	No recommended replacement
UMMA-1200-0250-1	No recommended replacement
UMMA-1200-0250-2	No recommended replacement
UMMA-1200-0300-1	No recommended replacement
UMMA-1200-0300-2	No recommended replacement
UMMA-1200-0400-1	No recommended replacement
UMMA-1200-0400-2	No recommended replacement
UMMA-1200-0500-1	No recommended replacement
UMMA-1200-0500-2	No recommended replacement

Product discontinuation	Recommended replacement
UMMA-1200-0600-1	No recommended replacement
UMMA-1200-0600-2	No recommended replacement
UMMA-1200-0750-1	No recommended replacement
UMMA-1200-0750-2	No recommended replacement
UMMA-1200-0800-1	No recommended replacement
UMMA-1200-0800-2	No recommended replacement
UMMA-1200-0900-1	No recommended replacement
UMMA-1200-0900-2	No recommended replacement
UMMA-1200-1000-1	No recommended replacement
UMMA-1200-1000-2	No recommended replacement
UMMA-1200-1250-1	No recommended replacement
UMMA-1200-1250-2	No recommended replacement
UMMA-1200-1500-1	No recommended replacement
UMMA-1200-1500-2	No recommended replacement
UMMA-1200-1750-1	No recommended replacement
UMMA-1200-1750-2	No recommended replacement
UMMA-1200-1800-1	No recommended replacement
UMMA-1200-1800-2	No recommended replacement
UMMA-1400-0400-1	No recommended replacement
UMMYA-0300-0250-1	No recommended replacement
UMMYA-0300-0250-2	No recommended replacement
UMMYA-0300-0300-1	No recommended replacement
UMMYA-0300-0300-2	No recommended replacement
UMMYA-0300-1250-1	No recommended replacement
UMMYA-0300-1250-2	No recommended replacement
UMMYA-0300-1500-1	No recommended replacement
UMMYA-0300-1500-2	No recommended replacement
UMMYA-0300-1750-1	No recommended replacement
UMMYA-0300-1750-2	No recommended replacement
UMMYA-0300-1800-1	No recommended replacement
UMMYA-0300-1800-2	No recommended replacement
UMMYA-0400-0250-1	No recommended replacement
UMMYA-0400-0250-2	No recommended replacement
UMMYA-0400-0300-1	No recommended replacement
UMMYA-0400-0300-2	No recommended replacement
UMMYA-0400-0400-1	No recommended replacement
UMMYA-0400-0400-2	No recommended replacement
UMMYA-0400-1250-1	No recommended replacement
UMMYA-0400-1250-2	No recommended replacement
UMMYA-0400-1500-1	No recommended replacement
UMMYA-0400-1500-2	No recommended replacement
UMMYA-0400-1750-1	No recommended replacement
UMMYA-0400-1750-2	No recommended replacement
UMMYA-0400-1800-1	No recommended replacement
UMMYA-0400-1800-2	No recommended replacement
UMMYA-0500-0250-1	No recommended replacement
UMMYA-0500-0250-2	No recommended replacement
UMMYA-0500-0300-1	No recommended replacement
UMMYA-0500-0300-2	No recommended replacement

Product discontinuation	Recommended replacement
UMMYA-0500-0400-1	No recommended replacement
UMMYA-0500-0400-2	No recommended replacement
UMMYA-0500-0500-1	No recommended replacement
UMMYA-0500-0500-2	No recommended replacement
UMMYA-0500-1250-1	No recommended replacement
UMMYA-0500-1250-2	No recommended replacement
UMMYA-0500-1500-1	No recommended replacement
UMMYA-0500-1500-2	No recommended replacement
UMMYA-0500-1750-1	No recommended replacement
UMMYA-0500-1750-2	No recommended replacement
UMMYA-0500-1800-1	No recommended replacement
UMMYA-0500-1800-2	No recommended replacement
UMMYA-0600-0250-1	No recommended replacement
UMMYA-0600-0250-2	No recommended replacement
UMMYA-0600-0300-1	No recommended replacement
UMMYA-0600-0300-2	No recommended replacement
UMMYA-0600-0400-1	No recommended replacement
UMMYA-0600-0400-2	No recommended replacement
UMMYA-0600-0500-1	No recommended replacement
UMMYA-0600-0500-2	No recommended replacement
UMMYA-0600-0600-1	No recommended replacement
UMMYA-0600-0600-2	No recommended replacement
UMMYA-0600-1250-1	No recommended replacement
UMMYA-0600-1250-2	No recommended replacement
UMMYA-0600-1500-1	No recommended replacement
UMMYA-0600-1500-2	No recommended replacement
UMMYA-0600-1750-1	No recommended replacement
UMMYA-0600-1750-2	No recommended replacement
UMMYA-0600-1800-1	No recommended replacement
UMMYA-0600-1800-2	No recommended replacement
UMMYA-0750-0250-1	No recommended replacement
UMMYA-0750-0250-2	No recommended replacement
UMMYA-0750-0300-1	No recommended replacement
UMMYA-0750-0300-2	No recommended replacement
UMMYA-0750-0400-1	No recommended replacement
UMMYA-0750-0400-2	No recommended replacement
UMMYA-0750-0500-1	No recommended replacement
UMMYA-0750-0500-2	No recommended replacement
UMMYA-0750-0600-1	No recommended replacement
UMMYA-0750-0600-2	No recommended replacement
UMMYA-0750-0750-1	No recommended replacement
UMMYA-0750-0750-2	No recommended replacement
UMMYA-0750-1250-1	No recommended replacement
UMMYA-0750-1250-2	No recommended replacement
UMMYA-0750-1500-1	No recommended replacement
UMMYA-0750-1500-2	No recommended replacement
UMMYA-0750-1750-1	No recommended replacement
UMMYA-0750-1750-2	No recommended replacement
UMMYA-0750-1800-1	No recommended replacement

Product discontinuation	Recommended replacement
UMMYA-0750-1800-2	No recommended replacement
UMMYA-0800-0250-1	No recommended replacement
UMMYA-0800-0250-2	No recommended replacement
UMMYA-0800-0300-1	No recommended replacement
UMMYA-0800-0300-2	No recommended replacement
UMMYA-0800-0400-1	No recommended replacement
UMMYA-0800-0400-2	No recommended replacement
UMMYA-0800-0500-1	No recommended replacement
UMMYA-0800-0500-2	No recommended replacement
UMMYA-0800-0600-1	No recommended replacement
UMMYA-0800-0600-2	No recommended replacement
UMMYA-0800-0750-1	No recommended replacement
UMMYA-0800-0750-2	No recommended replacement
UMMYA-0800-0800-1	No recommended replacement
UMMYA-0800-0800-2	No recommended replacement
UMMYA-0800-1250-1	No recommended replacement
UMMYA-0800-1250-2	No recommended replacement
UMMYA-0800-1500-1	No recommended replacement
UMMYA-0800-1500-2	No recommended replacement
UMMYA-0800-1750-1	No recommended replacement
UMMYA-0800-1750-2	No recommended replacement
UMMYA-0800-1800-1	No recommended replacement
UMMYA-0800-1800-2	No recommended replacement
UMMYA-0900-0250-1	No recommended replacement
UMMYA-0900-0250-2	No recommended replacement
UMMYA-0900-0300-1	No recommended replacement
UMMYA-0900-0300-2	No recommended replacement
UMMYA-0900-0400-1	No recommended replacement
UMMYA-0900-0400-2	No recommended replacement
UMMYA-0900-0500-1	No recommended replacement
UMMYA-0900-0500-2	No recommended replacement
UMMYA-0900-0600-1	No recommended replacement
UMMYA-0900-0600-2	No recommended replacement
UMMYA-0900-0750-1	No recommended replacement
UMMYA-0900-0750-2	No recommended replacement
UMMYA-0900-0800-1	No recommended replacement
UMMYA-0900-0800-2	No recommended replacement
UMMYA-0900-0900-1	No recommended replacement
UMMYA-0900-0900-2	No recommended replacement
UMMYA-0900-1250-1	No recommended replacement
UMMYA-0900-1250-2	No recommended replacement
UMMYA-0900-1500-1	No recommended replacement
UMMYA-0900-1500-2	No recommended replacement
UMMYA-0900-1750-1	No recommended replacement
UMMYA-0900-1750-2	No recommended replacement
UMMYA-0900-1800-1	No recommended replacement
UMMYA-0900-1800-2	No recommended replacement
UMMYA-1000-0250-1	No recommended replacement
UMMYA-1000-0250-2	No recommended replacement

Product discontinuation	Recommended replacement
UMMYA-1000-0300-1	No recommended replacement
UMMYA-1000-0300-2	No recommended replacement
UMMYA-1000-0400-1	No recommended replacement
UMMYA-1000-0400-2	No recommended replacement
UMMYA-1000-0500-1	No recommended replacement
UMMYA-1000-0500-2	No recommended replacement
UMMYA-1000-0600-1	No recommended replacement
UMMYA-1000-0600-2	No recommended replacement
UMMYA-1000-0750-1	No recommended replacement
UMMYA-1000-0750-2	No recommended replacement
UMMYA-1000-0800-1	No recommended replacement
UMMYA-1000-0800-2	No recommended replacement
UMMYA-1000-0900-1	No recommended replacement
UMMYA-1000-0900-2	No recommended replacement
UMMYA-1000-1000-1	No recommended replacement
UMMYA-1000-1000-2	No recommended replacement
UMMYA-1000-1250-1	No recommended replacement
UMMYA-1000-1250-2	No recommended replacement
UMMYA-1000-1500-1	No recommended replacement
UMMYA-1000-1500-2	No recommended replacement
UMMYA-1000-1750-1	No recommended replacement
UMMYA-1000-1750-2	No recommended replacement
UMMYA-1000-1800-1	No recommended replacement
UMMYA-1000-1800-2	No recommended replacement
UMMYA-1100-0250-1	No recommended replacement
UMMYA-1100-0250-2	No recommended replacement
UMMYA-1100-0300-1	No recommended replacement
UMMYA-1100-0300-2	No recommended replacement
UMMYA-1100-0400-1	No recommended replacement
UMMYA-1100-0400-2	No recommended replacement
UMMYA-1100-0500-1	No recommended replacement
UMMYA-1100-0500-2	No recommended replacement
UMMYA-1100-0600-1	No recommended replacement
UMMYA-1100-0600-2	No recommended replacement
UMMYA-1100-0750-1	No recommended replacement
UMMYA-1100-0750-2	No recommended replacement
UMMYA-1100-0800-1	No recommended replacement
UMMYA-1100-0800-2	No recommended replacement
UMMYA-1100-0900-1	No recommended replacement
UMMYA-1100-0900-2	No recommended replacement
UMMYA-1100-1000-1	No recommended replacement
UMMYA-1100-1000-2	No recommended replacement
UMMYA-1100-1250-1	No recommended replacement
UMMYA-1100-1250-2	No recommended replacement
UMMYA-1100-1500-1	No recommended replacement
UMMYA-1100-1500-2	No recommended replacement
UMMYA-1100-1750-1	No recommended replacement
UMMYA-1100-1750-2	No recommended replacement
UMMYA-1100-1800-1	No recommended replacement

Product discontinuation	Recommended replacement
UMMYA-1100-1800-2	No recommended replacement
UMMYA-1200-0250-1	No recommended replacement
UMMYA-1200-0250-2	No recommended replacement
UMMYA-1200-0300-1	No recommended replacement
UMMYA-1200-0300-2	No recommended replacement
UMMYA-1200-0400-1	No recommended replacement
UMMYA-1200-0400-2	No recommended replacement
UMMYA-1200-0500-1	No recommended replacement
UMMYA-1200-0500-2	No recommended replacement
UMMYA-1200-0600-1	No recommended replacement
UMMYA-1200-0600-2	No recommended replacement
UMMYA-1200-0750-1	No recommended replacement
UMMYA-1200-0750-2	No recommended replacement
UMMYA-1200-0800-1	No recommended replacement
UMMYA-1200-0800-2	No recommended replacement
UMMYA-1200-0900-1	No recommended replacement
UMMYA-1200-0900-2	No recommended replacement
UMMYA-1200-1000-1	No recommended replacement
UMMYA-1200-1000-2	No recommended replacement
UMMYA-1200-1250-1	No recommended replacement
UMMYA-1200-1250-2	No recommended replacement
UMMYA-1200-1500-1	No recommended replacement
UMMYA-1200-1500-2	No recommended replacement
UMMYA-1200-1750-1	No recommended replacement
UMMYA-1200-1750-2	No recommended replacement
UMMYA-1200-1800-1	No recommended replacement
UMMYA-1200-1800-2	No recommended replacement
UMOC	No recommended replacement
UMOC-4	No recommended replacement
UMRT4	No recommended replacement
UMRT8	No recommended replacement
UMRT8A	No recommended replacement
UMTHW	No recommended replacement
UMYA-12-12-1	No recommended replacement
UMYA-12-12-2	No recommended replacement
UMYA-12-18-1	No recommended replacement
UMYA-12-18-2	No recommended replacement
UMYA-12-24-1	No recommended replacement
UMYA-12-24-2	No recommended replacement
UMYA-12-30-1	No recommended replacement
UMYA-12-30-2	No recommended replacement
UMYA-12-36-1	No recommended replacement
UMYA-12-36-2	No recommended replacement
UMYA-12-42-1	No recommended replacement
UMYA-12-42-2	No recommended replacement
UMYA-12-48-1	No recommended replacement
UMYA-12-48-2	No recommended replacement
UMYA-12-54-1	No recommended replacement
UMYA-12-54-2	No recommended replacement

Product discontinuation	Recommended replacement
UMYA-12-60-1	No recommended replacement
UMYA-12-60-2	No recommended replacement
UMYA-12-66-1	No recommended replacement
UMYA-12-66-2	No recommended replacement
UMYA-12-72-1	No recommended replacement
UMYA-12-72-2	No recommended replacement
UMYA-18-12-1	No recommended replacement
UMYA-18-12-2	No recommended replacement
UMYA-18-18-1	No recommended replacement
UMYA-18-18-2	No recommended replacement
UMYA-18-24-1	No recommended replacement
UMYA-18-24-2	No recommended replacement
UMYA-18-30-1	No recommended replacement
UMYA-18-30-2	No recommended replacement
UMYA-18-36-1	No recommended replacement
UMYA-18-36-2	No recommended replacement
UMYA-18-42-1	No recommended replacement
UMYA-18-42-2	No recommended replacement
UMYA-18-48-1	No recommended replacement
UMYA-18-48-2	No recommended replacement
UMYA-18-54-1	No recommended replacement
UMYA-18-54-2	No recommended replacement
UMYA-18-60-1	No recommended replacement
UMYA-18-60-2	No recommended replacement
UMYA-18-66-1	No recommended replacement
UMYA-18-66-2	No recommended replacement
UMYA-18-72-1	No recommended replacement
UMYA-18-72-2	No recommended replacement
UMYA-24-12-1	No recommended replacement
UMYA-24-12-2	No recommended replacement
UMYA-24-18-1	No recommended replacement
UMYA-24-18-2	No recommended replacement
UMYA-24-24-1	No recommended replacement
UMYA-24-24-2	No recommended replacement
UMYA-24-30-1	No recommended replacement
UMYA-24-30-2	No recommended replacement
UMYA-24-36-1	No recommended replacement
UMYA-24-36-2	No recommended replacement
UMYA-24-42-1	No recommended replacement
UMYA-24-42-2	No recommended replacement
UMYA-24-48-1	No recommended replacement
UMYA-24-48-2	No recommended replacement
UMYA-24-54-1	No recommended replacement
UMYA-24-54-2	No recommended replacement
UMYA-24-60-1	No recommended replacement
UMYA-24-60-2	No recommended replacement
UMYA-24-66-1	No recommended replacement
UMYA-24-66-2	No recommended replacement
UMYA-24-72-1	No recommended replacement

Product discontinuation	Recommended replacement
UMYA-24-72-2	No recommended replacement
UMYA-30-12-1	No recommended replacement
UMYA-30-12-2	No recommended replacement
UMYA-30-18-1	No recommended replacement
UMYA-30-18-2	No recommended replacement
UMYA-30-24-1	No recommended replacement
UMYA-30-24-2	No recommended replacement
UMYA-30-30-1	No recommended replacement
UMYA-30-30-2	No recommended replacement
UMYA-30-36-1	No recommended replacement
UMYA-30-36-2	No recommended replacement
UMYA-30-42-1	No recommended replacement
UMYA-30-42-2	No recommended replacement
UMYA-30-48-1	No recommended replacement
UMYA-30-48-2	No recommended replacement
UMYA-30-54-1	No recommended replacement
UMYA-30-54-2	No recommended replacement
UMYA-30-60-1	No recommended replacement
UMYA-30-60-2	No recommended replacement
UMYA-30-66-1	No recommended replacement
UMYA-30-66-2	No recommended replacement
UMYA-30-72-1	No recommended replacement
UMYA-30-72-2	No recommended replacement
UMYA-36-12-1	No recommended replacement
UMYA-36-12-2	No recommended replacement
UMYA-36-18-1	No recommended replacement
UMYA-36-18-2	No recommended replacement
UMYA-36-24-1	No recommended replacement
UMYA-36-24-2	No recommended replacement
UMYA-36-30-1	No recommended replacement
UMYA-36-30-2	No recommended replacement
UMYA-36-36-1	No recommended replacement
UMYA-36-36-2	No recommended replacement
UMYA-36-42-1	No recommended replacement
UMYA-36-42-2	No recommended replacement
UMYA-36-48-1	No recommended replacement
UMYA-36-48-2	No recommended replacement
UMYA-36-54-1	No recommended replacement
UMYA-36-54-2	No recommended replacement
UMYA-36-60-1	No recommended replacement
UMYA-36-60-2	No recommended replacement
UMYA-36-66-1	No recommended replacement
UMYA-36-66-2	No recommended replacement
UMYA-36-72-1	No recommended replacement
UMYA-36-72-2	No recommended replacement
UMYA-42-12-1	No recommended replacement
UMYA-42-12-2	No recommended replacement
UMYA-42-18-1	No recommended replacement
UMYA-42-18-2	No recommended replacement

Product discontinuation	Recommended replacement
UMYA-42-24-1	No recommended replacement
UMYA-42-24-2	No recommended replacement
UMYA-42-30-1	No recommended replacement
UMYA-42-30-2	No recommended replacement
UMYA-42-36-1	No recommended replacement
UMYA-42-36-2	No recommended replacement
UMYA-42-42-1	No recommended replacement
UMYA-42-42-2	No recommended replacement
UMYA-42-48-1	No recommended replacement
UMYA-42-48-2	No recommended replacement
UMYA-42-54-1	No recommended replacement
UMYA-42-54-2	No recommended replacement
UMYA-42-60-1	No recommended replacement
UMYA-42-60-2	No recommended replacement
UMYA-42-66-1	No recommended replacement
UMYA-42-66-2	No recommended replacement
UMYA-42-72-1	No recommended replacement
UMYA-42-72-2	No recommended replacement
UMYA-48-12-1	No recommended replacement
UMYA-48-12-2	No recommended replacement
UMYA-48-18-1	No recommended replacement
UMYA-48-18-2	No recommended replacement
UMYA-48-24-1	No recommended replacement
UMYA-48-24-2	No recommended replacement
UMYA-48-30-1	No recommended replacement
UMYA-48-30-2	No recommended replacement
UMYA-48-36-1	No recommended replacement
UMYA-48-36-2	No recommended replacement
UMYA-48-42-1	No recommended replacement
UMYA-48-42-2	No recommended replacement
UMYA-48-48-1	No recommended replacement
UMYA-48-48-2	No recommended replacement
UMYA-48-54-1	No recommended replacement
UMYA-48-54-2	No recommended replacement
UMYA-48-60-1	No recommended replacement
UMYA-48-60-2	No recommended replacement
UMYA-48-66-1	No recommended replacement
UMYA-48-66-2	No recommended replacement
UMYA-48-72-1	No recommended replacement
UMYA-48-72-2	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.