

Product Discontinuation Notices

Issue Date
March 1, 2024

Product Discontinuation

Pushbutton switches and Indicators

- A16 series some items**
- M16 series some items**
- A3P series some items**
- M2P series some items**
- VAQ series some items**
- ZAP series some items**



Recommended Replacement

No recommended replacement

[Final order entry date]

The end of March, 2025

[Date of The Last Shipping]

The end of June, 2025

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement
A16-AGA-2S	No recommended replacement
A16-AYA-2S	No recommended replacement
A16-JBA-2S	No recommended replacement
A16-TGA-2S	No recommended replacement
A165-AAA-2	No recommended replacement
A165-AWA-2S	No recommended replacement
A165K-T2MR-2S	No recommended replacement
A165K-T3MR-2S	No recommended replacement
A165L-AYM-12D-2	No recommended replacement
A165L-JYA-T2-2S	No recommended replacement
A165L-TWA-5D-2	No recommended replacement
A165L-TWA-T1-2S	No recommended replacement
A165W-A2MG-T1-1	No recommended replacement
A165W-A2MG-T1-2	No recommended replacement
A165W-A2MR-T1-2	No recommended replacement
A165W-A3AY	No recommended replacement
A165W-J2MR-T1-2S	No recommended replacement
A165W-J3MG-T1-2	No recommended replacement
A165W-T2MG-T2-2S	No recommended replacement
A165W-T3MG-T1-2	No recommended replacement
A16L-A-12D-2P	No recommended replacement
A16L-A-12D-2S	No recommended replacement
A16L-A-24D-1P	No recommended replacement
A16L-A-24D-2P	No recommended replacement
A16L-A-5D-1P	No recommended replacement
A16L-A-5D-2P	No recommended replacement
A16L-AAA-24D-2S	No recommended replacement

Product discontinuation	Recommended replacement
A16L-AAA-5D-1	No recommended replacement
A16L-AAA-T1-1	No recommended replacement
A16L-AGA-12D-2S	No recommended replacement
A16L-AGA-5D-2S	No recommended replacement
A16L-APWM-24D-2S	No recommended replacement
A16L-APYA-24D-2S	No recommended replacement
A16L-APYA-T1-2	No recommended replacement
A16L-APYM-T1-1	No recommended replacement
A16L-AYA-T1-2S	No recommended replacement
A16L-G-12D-1P	No recommended replacement
A16L-G-12D-2P	No recommended replacement
A16L-G-12D-2S	No recommended replacement
A16L-G-5D-1P	No recommended replacement
A16L-G-5D-2P	No recommended replacement
A16L-G-5D-2S	No recommended replacement
A16L-JPYA-T2-2S	No recommended replacement
A16L-JPYM-T1-2	No recommended replacement
A16L-R-12D-2P	No recommended replacement
A16L-R-12D-2S	No recommended replacement
A16L-R-24D-1P	No recommended replacement
A16L-R-5D-1P	No recommended replacement
A16L-R-5D-2P	No recommended replacement
A16L-R-5D-2S	No recommended replacement
A16L-TAM-T1-2S	No recommended replacement
A16L-TPYA-12D-2S	No recommended replacement
A16L-TPYM-T1-1	No recommended replacement
A16L-W-12D-2P	No recommended replacement
A16L-W-24D-1P	No recommended replacement
A16L-W-5D-1P	No recommended replacement
A16L-W-5D-2P	No recommended replacement
A16L-W-5D-2S	No recommended replacement
A16L-Y-12D-1P	No recommended replacement
A16L-Y-12D-2P	No recommended replacement
A16L-Y-24D-1P	No recommended replacement
A16L-Y-24D-2P	No recommended replacement
A16L-Y-5D-1P	No recommended replacement
A16L-Y-5D-2P	No recommended replacement
A16L-Y-5D-2S	No recommended replacement
A16W-3NR-T2-2S	No recommended replacement
A16W-3NY-24D-2S	No recommended replacement
A3PA-5600-A	No recommended replacement
A3PA-5705-24E	No recommended replacement
A3PA-90A12-12EW	No recommended replacement
A3PA-90C12-12EG	No recommended replacement
A3PA-90C12-12ER	No recommended replacement
A3PJ-5600-A	No recommended replacement
A3PJ-7170-1	No recommended replacement
A3PJ-90D11-05EW	No recommended replacement
A3PT-7011	No recommended replacement

Product discontinuation	Recommended replacement
A3PT-7070-2	No recommended replacement
A3PT-90B12-24CW	No recommended replacement
M16-JG-5D-S	No recommended replacement
M165-JA-12D	No recommended replacement
M165-JY-5D	No recommended replacement
M2PA-5702-05E	No recommended replacement
M2PA-5706-05E	No recommended replacement
VAQ-37B VX-01-1C23	No recommended replacement
VAQR-4A	No recommended replacement
ZAP-1A	No recommended replacement
2ZAP-2A	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.