



**Product Discontinuation**  
Terminal Blocks XW5G/S/T



**No recommended replacement**

### [ Final order entry date ]

The items has been discontinued with immediate effect.

### [ Product discontinuation and recommended replacement ]

Product discontinuation	Recommended replacement
XW5G-S70-1.1-1	No recommended replacement
XW5S-S2.5-3	No recommended replacement
XW5T-S70-1.1-1	No recommended replacement
XW5G-S4.0-1.1-2	No recommended replacement
XW5S-S2.5-3N	No recommended replacement
XW5S-S16-2	No recommended replacement
XW5T-S70-1.1-1BL	No recommended replacement
XW5S-S2.5-4	No recommended replacement
XW5T-S150-1.1-1BL	No recommended replacement
XW5S-S2.5-5N	No recommended replacement
XW5T-S4.0-1.2-1BL	No recommended replacement
XW5S-S6.0-4	No recommended replacement
XW5G-S4.0-1.2-1	No recommended replacement
XW5T-S150-1.1-1	No recommended replacement