

The unavailability of legacy part numbers has forced OMRON Microscan to decide the EOL announcement of some **HS-360X accessories**. Since the **V450-H accessories** are essentially the same as the **HS-360X Accessories**, equivalent **V450-H accessories** may be used as a direct replacement.

### Product Discontinuation

Name of Category



#### HS-360X Accessories

12-9000937-01 | 98-9000□□□-0□



### Recommended Replacement

Name of Category

#### V450-H Accessories

V450-AK0 | V450-A□□-1

### [ Final order entry date ]

The end of December 2025

**NOTE:** Acceptance and shipment of Final Orders are subject to product availability due to limited quantities on hand and scarcity of key components. However, since the V450-H is essentially the same product with just a different branding and part numbering, an equivalent V450-H accessory will be shipped in case of such availability issues.

### [ Date of The Last Shipping ]

The end of December 2025

### [ Scheduled date of maintenance close ]

The end of December 2027

**NOTE:** Maintenance is subject to product and component availability. Since the V450-H accessories are essentially the same as the HS-360X accessories, equivalent V450-H accessories may be used to fulfill maintenance.

### [ Difference from discontinued product ]

Recommended replacement Model	Body Color	Dimensions	Wire connection	Mounting Dimensions	Characteristics	Operation ratings	Operation methods
V450-AK0	*	**	**	**	**	**	**
V450-A□□-1	*	**	**	**	**	**	**

\*\* : Compatible

\* : The change is a little/Almost compatible

-- : Not compatible



- : No corresponding specification

## [ Product Discontinuation and recommended replacement ]

Product discontinuation	Recommended replacement*
12-9000937-01	V450-AK0
98-9000181-01	V450-AC0-1
98-9000182-01	V450-AC1-1
98-9000186-01	V450-AS0-1
98-9000185-01	V450-AG0-1
98-9000224-01	V450-AB0-1
98-9000224-02	V450-AB1-1

\*All V450 accessories are interchangeable with the replaced part numbers. In many cases, the only difference lies in the brand (Microscan ↔ OMRON, please see below) and packaging labeling.

## [ Body color ]

Product discontinuation Model 12-9000937-01 (for reference)	Recommended replacement Model V450-AK0 (for reference)
<p>Microscan branding</p> 	<p>Omron branding</p> 

## [Other features]

Fully compatible.

Specifications and prices in this product news are as of the issue date and are subject to change without notice.  
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.